

Passcert

Higher Quality, better service!



Q&A

[Http://www.passcert.com](http://www.passcert.com)

We offer free update service for one year.

Exam : 6002.1

**Title : Avaya Aura(TM)
Communication Manager
and CM Messaging (R6.0)
Implementation Exam**

Version : DEMO

1. When troubleshooting a system fault, if the web interface or SAT are unavailable, which method should be used?

- A. SAL
- B. TTY2
- C. CLI
- D. MODEM

Answer: C

2. Which two series support RAID 5 configuration for CM6.0? (Choose two)

- A. S8730 Server with 8 GB RAM
- B. S8800 Server with 12 GB RAM
- C. S8510 Server with 8 GB RAM
- D. S8300D Server with 8 GB RAM

Answer: B,C

3. Hunt group number 99, with group extension 4199, is administered for messaging.

Which command needs to be executed at the SAT terminal to troubleshoot hunt group 99?

- A. Show tracelog huntgroup 4199
- B. View logs real time huntgroup 99
- C. Display real time logs hunt group 99
- D. List trace hunt-group 4199

Answer: D

4. A customer needs to set up SIP integration on Communication Manager Messaging Application

What are three pieces of information that are needed to meet this requirement? (Choose three)

- A. Signaling group number
- B. SIP domain
- C. Transport Method
- D. Extension length
- E. Hunt Group number

Answer: B,C,D

5.Which three are tests that can be performed to Verify a communication manager Messaging 6.0 application is working properly? (Choose three)

- A. Verify the hunt group status
- B. Check the messaging port status using the display port command
- C. Call the messaging Hunt Group
- D. Check the messaging port status using the status port command
- E. Perform message waiting indication test

Answer: A,C,E

6.On a media gateway G450, which slots are permitted for the MM 342?

- A. V1 and V2
- B. V6 and V6
- C. V3 and V8
- D. V5 and V7

Answer: C

7.A customer is planning to upgrade from CM 5X to CM 6.0 an existing 8510 server.

What is the total minimum memory requirement for this upgrade?

- A. 4 GB RAM
- B. 8 GB RAM
- C. 12 GB RAM
- D. 16 GB RAM

Answer: B

8.Which screen is used while upgrading the system platform from release 6.0.0.09 to release 6.0.0.11?

- A. Communication manager Web interface
- B. Console domain Server Management Path management
- C. Console domain Server Management Platform Upgrade

D. Console domain Virtual Machine Management

Answer: C

9.Which three statements about CM_Duplex CM 6.0 are true?

- A. Software duplication is available, but hardware duplication is not available.
- B. The S8510 server is not used for duplication
- C. Server duplication is configured via “Failover” option on CDRoms web interface
- D. S8730 with DAL 2 card does not support server duplication in CM 6.0.
- E. The CM duplex template supports CMM

Answer: A,B,D

10.Which gateway command resets the Gateway back to factory default?

- A. Reset
- B. Restart
- C. Softboot
- D. Nvram init

Answer: D